



Gear Cutter

Primary Job Functions

Primary responsibility will be the set-up and operation of gear cutter machines in the medium cell. Also inspection of work performed, keeping the area clean and assisting others as time allows.

Knowledge and Skill Requirements

Qualified candidates should have a minimum of two years experience running gear cutting machines. Other required skills include blue print reading and crane operating. Individuals need to be highly motivated, reliable, flexible and highly proficient with mathematics and a person who works well with others.

Send cover letter and detailed resume to: hr-info@horsburgh-scott.com